ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M01455
Date Received: 11/08/07
Date Extracted: 11/13/07
Date Analyzed: 11/13/07
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: PO M01455, F&BI 711134
Lab ID: 711134-01 x10

Lab ID: 711134-01 x10
Data File: 711134-01 x10.090
Instrument: ICPMS1

Operator: HR

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 92 60 125

Concentration
Analyte: ug/L (ppb)

Chromium 389
Nickel 411
Copper 261
Zinc <10

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Client: Alaskan Copper Works PO M01455, F&BI 711134 Date Received: Not Applicable Project: Date Extracted: 11/13/07 Lab ID: 17-419 mb Date Analyzed: 11/13/07 Data File: I7-419 mb.074 ICPMS1 Matrix: Water Instrument: Units: ug/L (ppb) Operator: HR

Lower Upper Internal Standard: % Recovery: Limit: Limit: Scantium 60 125
Germanium 109 60 125

Analyte: Concentration ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 11/27/07 Date Received: 11/08/07

Project: Metro Self Monitor, PO M01455, F&BI 711134

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 711159-01 (Duplicate)

		Sample	Duplicate	Relative Percent	Acceptan	ıce
Analyte	Reporting Units	Result	Result	Difference	Criteria	a
Chromium	ug/L (ppb)	<1	<1	nm	0-20	
Nickel	ug/L (ppb)	<1	<1	nm	0-20	
Copper	ug/L (ppb)	1.25	1.23	2	0-20	
Zinc	ug/L (ppb)	1.69	2.88	52 a	0-20	

Laboratory Code: 711159-01 (Matrix Spike)

		CANAL MINE		Percen	t		
ghaireach i inte		Spike	Sample	Recover	у	Acceptance	e
Analyte	Reporting Un	its Level	Result	MS	14.50	Criteria	9
Chromium	ug/L (ppb)	20	<1	102		50-150	* V 2 32 4 - N 2 32 4
Nickel	ug/L (ppb)	20	<1	102		50-150	
Copper	ug/L (ppb)	20	1.25	96		50-150	17.
Zinc	ug/L (ppb)	50	1.69	95		50-150	

Laboratory Code: Laboratory Control Sample

		Spike	Percent Recovery		e
Analyte	Reporting Unit	s Level	LCS	Criteria	No.
Chromium	ug/L (ppb)	20	98	70-130	TV.
Nickel	ug/L (ppb)	20	100	70-130	
Copper	ug/L (ppb)	20	99	70-130	
Zinc	ug/L (ppb)	50	83	70-130	

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- fp Compounds in the sample matrix interfered with quantitation of the analyte. The reported concentration may be a false positive.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

November 27, 2007



INVOICE #07ACU1127-1

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M01455, F&BI 711134 - Results of testing requested by Gerry Thompson for material submitted on November 8, 2007.

FEDERAL TAX ID #(b) (6)

711134		manne entrescribe tres distributed and more communi	SAM	IPLE CHAI	N OF C	JSTC	DY	^	1E	11- 2	S _ C	7		AIY		
Send Report To SERALD THOMPSON Company ALASKAN Copper Works Address 628 S. HANFORD ST City, State, ZIP SEATTLE UND 98134				SAMPLERS (signature) PROJECT NAME/NO. PO# Mestro Self Monitor M01455 REMARKS								Page # of TURNAROUND TIME Standard (2 Weeks) RUSH				
Phone # 206-571-6033 Fax # 206-382-4309											☐ Return samples ☐ Will call with instructions					
						7	П			SES RI	QUE	STED	· 	2		
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	Cec ween				Notes		
MO1455	01	11/8/07	12:45	HZO	1					1						
,				1		l		1 1				- 1		l .		

									.				1						
r				,															
	. ,			į								<i>'</i>							
Friedman & Bruya, Inc.		SIGNATU	PRINT NAME							COMPANY					DATE	MIT	E		
3012 16th Avenue West	Relinquished by:					GERALD THOMPSON							ACW					2:30	بهرد
Seattle, WA 98119-2029	Received by: M. C.					Man Phan						FEBI					8/07	V	
Ph. (206) 285-8282	Relinquished by:															. 1	1		
Fax (206) 283-5044	Received by:							7			-		· · · · · ·						
FORMS\COC\COC.DOC	L <u> </u>				J						<u> </u>						20		
	į .										S	am	ples	recei	ved:	ata	20°C		

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

November 27, 2007

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on November 8, 2007 from the Metro Self Monitor, PO M01455, F&BI 711134 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU1127R.DOC